




Xenotech Arc

A little study of these diagrams is the best way to get a feel for Beginning & Ending Angles in the Xenotech toolkit.
See Brewer Sales FAXonDemand doc# 150 for a step by step example of matching POS/NEG arcs

ANGLEPOS.XOT



ANGLENEG.XOT

